SUBJECT INDEX

Brick masonry

Brick Masonry: U.S. Office Building in Moscow, James G. Gross, Robert G. Mathey, Charles Scribner and William C. Stone, CF Feb. 89 p35-56.

Brittle fractures

Ashland Tank Collapse Investigation, John L. Gross, John H. Smith and Richard N. Wright, CF Aug. 89 p144-162.

Brittle Fracture and Collapse of Large Grain-Storage Tank, German Gurfinkel, CF Aug. 89 p163-183.

Building codes

Two Roof Failures Due to Water Ponding and Related Code Requirements, Luis F. Estenssoro, CF Aug. 89 p184-190.

Building design

Assessment: U.S. Office Building in Moscow, Richard N. Wright, Nicholas J. Carino, James G. Gross and Mary Sansalone, CF Feb. 89 p2-15.

Performance and Building: Problems of Evaluation, R. A. Mohsini, CF Nov. 89 p235-242.

Building, office

Brick Masonry: U.S. Office Building in Moscow, James G. Gross, Robert G. Mathey, Charles Scribner and William C. Stone, CF Feb. 89 p35-56.

Buildings

Mediation that Worked: Role of OSHA in L'Ambiance Plaza Settlement, Michael D. Felsen, CF Nov. 89 p212-217.

Performance and Building: Problems of Evaluation, R. A. Mohsini, CF Nov. 89 p235-242.

Buildings, office

Assessment: U.S. Office Building in Moscow, Richard N. Wright, Nicholas J. Carino, James G. Gross and Mary Sansalone, CF Feb. 89 p2-15.

Progressive Collapse: U.S. Office Building in Moscow, Felix Y. Yokel, Richard N. Wright and William C. Stone, CF Feb. 89 p57-75.

Structure: U.S. Office Building in Moscow, Nicholas Carino, William C. Stone, Mary Sansalone, Felix Y. Yokel, Erik M. Hendrickson, Emil Simiu, James G. Gross and Richard N. Wright, CF Feb. 89 p16-34.

Case reports

Investigative Studies of Ceiling Collapses, Fabian C. Hadipriono, CF Feb. 88 p44-51.

Ceilings

Investigative Studies of Ceiling Collapses, Fabian C. Hadipriono, CF Feb. 88 p44-51.

Chromates

Performance of Some Structures Constructed on Chromium Ore Fills, Dorairaja Raghu and Hsin-Neng Hsieh, CF May 89 p113-120.

Collapse

Ashland Tank Collapse Investigation, John L. Gross, John H. Smith and Richard N. Wright, CF Aug. 89 p144-162.

Brittle Fracture and Collapse of Large Grain-Storage Tank, German Gurfinkel, CF Aug. 89 p163-183.

Collapse and Repair of Tall Concrete Silos with Suspended Steel Hopper, German Gurfinkel, CF Nov. 89 p243-264.

Investigation of the Collapse of L'Ambiance Plaza, Charles F. Scribner and Charles G. Culver, CF May 88 p58-79.

Investigative Studies of Ceiling Collapses, Fabian C. Hadipriono, CF Feb. 88 p44-51.

Mediation that Worked: Role of OSHA in L'Ambiance Plaza Settlement, Michael D. Felsen, CF Nov. 89 p212-217.

Collapse load

Roof Collapse Under Snowdrift Loading and Snow Drift Design Criteria, Rubin M. Zallen, CF May 88 p80-98.

Concrete deterioration

Performance of Some Structures Constructed on Chromium Ore Fills, Dorairaja Raghu and Hsin-Neng Hsieh, CF May 89 p113-120.

Concrete, precast

Progressive Collapse: U.S. Office Building in Moscow, Felix Y. Yokel, Richard N. Wright and William C. Stone, CF Feb. 89 p57-75.

Concrete, reinforced

Collapse and Repair of Tall Concrete Silos with Suspended Steel Hopper, German Gurfinkel, CF Nov. 89 p243-264.

Restoring an Impaired Concrete Silo, German Gurfinkel, CF May 89 p87-99.

Construction

Practical Quality-Controlled Construction, Harvey A. Kagan, CF Aug. 89 p191-198.

Construction costs

Practical Quality-Controlled Construction, Harvey A. Kagan, CF Aug. 89 p191-198.

Construction inspection

Assessment: U.S. Office Building in Moscow, Richard N. Wright, Nicholas J. Carino, James G. Gross and Mary Sansalone, CF Feb. 89 p2-15.

Brick Masonry: U.S. Office Building in Moscow, James G. Gross, Robert G. Mathey, Charles Scribner and William C. Stone, CF Feb. 89 p35-56.

Project Peer Review: Results of the Structural Failures II Conference, Glenn R. Bell, Frank W. Kan and David R. Wright, CF Nov. 89 p218-225.

Construction materials

Construction Materials Quality Management, George Stukhart, CF May 89 p100-112.

Construction site accidents

Investigation of the Collapse of L'Ambiance Plaza, Charles F. Scribner and Charles G. Culver, CF May 88 p58-79.

Corrosion

Restoring an Impaired Concrete Silo, German Gurfinkel, CF May 89 p87-99.

Cracking

Restoring an Impaired Concrete Silo, German Gurfinkel, CF May 89 p87-99.

Cracks

Brittle Fracture and Collapse of Large Grain-Storage Tank, German Gurfinkel, CF Aug. 89 p163-183.

Design

Limitations in Decision Making and System Performance, J. C. Santamarina and J. L. Chameau, CF May 89 p78-86.

Practical Quality-Controlled Construction, Harvey A. Kagan, CF Aug. 89 p191-198.

Engineering

Limitations in Decision Making and System Performance, J. C. Santamarina and J. L. Chameau, CF May 89 p78-86.

Errors

Limitations in Decision Making and System Performance, J. C. Santamarina and J. L. Chameau, CF May 89 p78-86.

Evaluation

Assessment: U.S. Office Building in Moscow, Richard N. Wright, Nicholas J. Carino, James G. Gross and Mary Sansalone, CF Feb. 89 p2-15.

Failures

Collapse and Repair of Tall Concrete Silos with Suspended Steel Hopper, German Gurfinkel, CF Nov. 89 p243-264.

Limitations in Decision Making and System Performance, J. C. Santamarina and J. L. Chameau, CF May 89 p78-86.

Project Peer Review: Results of the Structural Failures II Conference, Glenn R. Bell, Frank W. Kan and David R. Wright, CF Nov. 89 p218-225.

Search for the Cause of High-Speed-Channel Revetment Failures, Enzo Levi and Efrain del Risco, CF May 89 p125-136.

Two Roof Failures Due to Water Ponding and Related Code Requirements, Luis F. Estenssoro, CF Aug. 89 p184-190.

Failures, investigation

Ashland Tank Collapse Investigation, John L. Gross, John H. Smith and Richard N. Wright, CF Aug. 89 p144-162.

Failures, investigations

Failures of 108-Inch Steel Pipe Water Main, Piotr D. Moncarz, John C. Shyne and George K. Derbalian, CF Aug. 87 p168-187.

Investigation of the Collapse of L'Ambiance Plaza, Charles F. Scribner and Charles G. Culver, CF May 88 p58-79.

Mediation that Worked: Role of OSHA in L'Ambiance Plaza Settlement, Michael D. Felsen, CF Nov. 89 p212-217.

Federal government

Assessment: U.S. Office Building in Moscow, Richard N. Wright, Nicholas J. Carino, James G. Gross and Mary Sansalone, CF Feb. 89 p2-15.

Brick Masonry: U.S. Office Building in Moscow, James G. Gross, Robert G. Mathey, Charles Scribner and William C. Stone, CF Feb. 89 p35-56.

Progressive Collapse: U.S. Office Building in Moscow, Felix Y. Yokel, Richard N. Wright and William C. Stone, CF Feb. 89 p57-75.

Structure: U.S. Office Building in Moscow, Nicholas Carino, William C. Stone, Mary Sansalone, Felix Y. Yokel, Erik M. Hendrickson, Emil Simiu, James G. Gross and Richard N. Wright, CF Feb. 89 p16-34.

Federal-state cooperation

Mediation that Worked: Role of OSHA in L'Ambiance Plaza Settlement, Michael D. Felsen, CF Nov. 89 p212-217.

Field investigations

Collapse and Repair of Tall Concrete Silos with Suspended Steel Hopper, German Gurfinkel, CF Nov. 89 p243-264.

Forensic engineering

Failures of 108-Inch Steel Pipe Water Main, Piotr D. Moncarz, John C. Shyne and George K. Derbalian, CF Aug. 87 p168-187.

Fracture strength

Brittle Fracture and Collapse of Large Grain-Storage Tank, German Gurfinkel, CF Aug. 89 p163-183.

Fractures

Ashland Tank Collapse Investigation, John L. Gross, John H. Smith and Richard N. Wright, CF Aug. 89 p144-162.

Grain storage

Brittle Fracture and Collapse of Large Grain-Storage Tank, German Gurfinkel, CF Aug. 89 p163-183.

Restoring an Impaired Concrete Silo, German Gurfinkel, CF May 89 p87-99.

Human behavior

Limitations in Decision Making and System Performance, J. C. Santamarina and J. L. Chameau, CF May 89 p78-86.

Human factors

Limitations in Decision Making and System Performance, J. C. Santamarina and J. L. Chameau, CF May 89 p78-86.

Hydraulics

Search for the Cause of High-Speed-Channel Revetment Failures, Enzo Levi and Efrain del Risco, CF May 89 p125-136.

Inspection

Construction Materials Quality Management, George Stukhart, CF May 89 p100-112.

Practical Quality-Controlled Construction, Harvey A. Kagan, CF Aug. 89 p191-198.

Interconnected systems

Performance and Building: Problems of Evaluation, R. A. Mohsini, CF Nov. 89 p235-242.

Joists

Roof Collapse Under Snowdrift Loading and Snow Drift Design Criteria, Rubin M. Zallen, CF May 88 p80-98.

Land fill

Performance of Some Structures Constructed on Chromium Ore Fills, Dorairaja Raghu and Hsin-Neng Hsieh, CF May 89 p113-120.

Leaching

Performance of Some Structures Constructed on Chromium Ore Fills, Dorairaja Raghu and Hsin-Neng Hsieh, CF May 89 p113-120.

Lift-slab construction

Investigation of the Collapse of L'Ambiance Plaza, Charles F. Scribner and Charles G. Culver, CF May 88 p58-79.

Liners

Restoring an Impaired Concrete Silo, German Gurfinkel, CF May 89 p87-99.

Load resistant design factor

Roof Collapse Under Snowdrift Loading and Snow Drift Design Criteria, Rubin M. Zallen, CF May 88 p80-98.

Load shifting

Roof Collapse Under Snowdrift Loading and Snow Drift Design Criteria, Rubin M. Zallen, CF May 88 p80-98.

Maintenance

Roof Collapse, Taxi Cab Company Garage, Champaign, Illinois, John A. Frauenhoffer, CF May 89 p121-124.

Materials

Construction Materials Quality Management, George Stukhart, CF May 89 p100-112.

Materials failure

Construction Materials Quality Management, George Stukhart, CF May 89 p100-112.

Materials testing

Construction Materials Quality Management, George Stukhart, CF May 89 p100-112.

Mediation

Mediation that Worked: Role of OSHA in L'Ambiance Plaza Settlement, Michael D. Felsen, CF Nov. 89 p212-217.

Models

Performance and Building: Problems of Evaluation, R. A. Mohsini, CF Nov. 89 p235-242.

Optimal design

Performance and Building: Problems of Evaluation, R. A. Mohsini, CF Nov. 89 p235-242.

Parapets

Brick Masonry: U.S. Office Building in Moscow, James G. Gross, Robert G. Mathey, Charles Scribner and William C. Stone, CF Feb. 89 p35-56.

Peer review

Project Peer Review: Results of the Structural Failures II Conference, Glenn R. Bell, Frank W. Kan and David R. Wright, CF Nov. 89 p218-225.

Performance evaluation

Performance and Building: Problems of Evaluation, R. A. Mohsini, CF Nov. 89 p235-242.

Pipe design

Failures of 108-Inch Steel Pipe Water Main, Piotr D. Moncarz, John C. Shyne and George K. Derbalian, CF Aug. 87 p168-187.

Ponding

Two Roof Failures Due to Water Ponding and Related Code Requirements, Luis F. Estenssoro, CF Aug. 89 p184-190.

Professional practice

Project Peer Review: Results of the Structural Failures II Conference, Glenn R. Bell, Frank W. Kan and David R. Wright, CF Nov. 89 p218-225.

Progressive failure

Investigation of the Collapse of L'Ambiance Plaza, Charles F. Scribner and Charles G. Culver, CF May 88 p58-79.

Investigative Studies of Ceiling Collapses, Fabian C. Hadipriono, CF Feb. 88 p44-51.

Progressive Collapse: U.S. Office Building in Moscow, Felix Y. Yokel, Richard N. Wright and William C. Stone, CF Feb. 89 p57-75.

Project management

Practical Quality-Controlled Construction, Harvey A. Kagan, CF Aug. 89 p191-198.

Project Peer Review: Results of the Structural Failures II Conference, Glenn R. Bell, Frank W. Kan and David R. Wright, CF Nov. 89 p218-225.

Quality assurance

Construction Materials Quality Management, George Stukhart, CF May 89 p100-112.

Practical Quality-Controlled Construction, Harvey A. Kagan, CF Aug. 89 p191-198.

Project Peer Review: Results of the Structural Failures II Conference, Glenn R. Bell, Frank W. Kan and David R. Wright, CF Nov. 89 p218-225.

Quality control

Construction Materials Quality Management, George Stukhart, CF May 89 p100-112.

Practical Quality-Controlled Construction, Harvey A. Kagan, CF Aug. 89 p191-198.

Project Peer Review: Results of the Structural Failures II Conference, Glenn R. Bell, Frank W. Kan and David R. Wright, CF Nov. 89 p218-225.

Rehabilitation

Roof Collapse, Taxi Cab Company Garage, Champaign, Illinois, John A. Frauenhoffer, CF May 89 p121-124.

Reinforcing steels

Restoring an Impaired Concrete Silo, German Gurfinkel, CF May 89 p87-99.

Retrofitting

Restoring an Impaired Concrete Silo, German Gurfinkel, CF May 89 p87-99.

Revetments

Search for the Cause of High-Speed-Channel Revetment Failures, Enzo Levi and Efrain del Risco, CF May 89 p125-136.

Roof failure

Roof Collapse, Taxi Cab Company Garage, Champaign, Illinois, John A. Frauenhoffer, CF May 89 p121-124.

Roof failures

Roof Collapse Under Snowdrift Loading and Snow Drift Design Criteria, Rubin M. Zallen, CF May 88 p80-98.

Two Roof Failures Due to Water Ponding and Related Code Requirements, Luis F. Estenssoro, CF Aug. 89 p184-190.

Salts effects

Performance of Some Structures Constructed on Chromium Ore Fills, Dorairaja Raghu and Hsin-Neng Hsieh, CF May 89 p113-120.

Shear

Roof Collapse, Taxi Cab Company Garage, Champaign, Illinois, John A. Frauenhoffer, CF May 89 p121-124.

Silos

Collapse and Repair of Tall Concrete Silos with Suspended Steel Hopper, German Gurfinkel, CF Nov. 89 p243-264.

Restoring an Impaired Concrete Silo, German Gurfinkel, CF May 89 p87-99.

Snowdrifts

Roof Collapse Under Snowdrift Loading and Snow Drift Design Criteria, Rubin M. Zallen, CF May 88 p80-98.

Spillways

Search for the Cause of High-Speed-Channel Revetment Failures, Enzo Levi and Efrain del Risco, CF May 89 p125-136.

Sprinklers

Two Roof Failures Due to Water Ponding and Related Code Requirements, Luis F. Estenssoro, CF Aug. 89 p184-190.

Standards

Progressive Collapse: U.S. Office Building in Moscow, Felix Y. Yokel, Richard N. Wright and William C. Stone, CF Feb. 89 p57-75.

Steel

Ashland Tank Collapse Investigation, John L. Gross, John H. Smith and Richard N. Wright, CF Aug. 89 p144-162.

Steel pipes

Failures of 108-Inch Steel Pipe Water Main, Piotr D. Moncarz, John C. Shyne and George K. Derbalian, CF Aug. 87 p168-187.

Steel plates

Restoring an Impaired Concrete Silo, German Gurfinkel, CF May 89 p87-99.

Steel structures

Collapse and Repair of Tall Concrete Silos with Suspended Steel Hopper, German Gurfinkel, CF Nov. 89 p243-264.

Strength

Brick Masonry: U.S. Office Building in Moscow, James G. Gross, Robert G. Mathey, Charles Scribner and William C. Stone, CF Feb. 89 p35-56.

Structural analysis

Brick Masonry: U.S. Office Building in Moscow, James G. Gross, Robert G. Mathey, Charles Scribner and William C. Stone, CF Feb. 89 p35-56.

Brittle Fracture and Collapse of Large Grain-Storage Tank, German Gurfinkel, CF Aug. 89 p163-183.

Progressive Collapse: U.S. Office Building in Moscow, Felix Y. Yokel, Richard N. Wright and William C. Stone, CF Feb. 89 p57-75.

Structure: U.S. Office Building in Moscow, Nicholas Carino, William C. Stone, Mary Sansalone, Felix Y. Yokel, Erik M. Hendrickson, Emil Simiu, James G. Gross and Richard N. Wright, CF Feb. 89 p16-34.

Structural design

Project Peer Review: Results of the Structural Failures II Conference, Glenn R. Bell, Frank W. Kan and David R. Wright, CF Nov. 89 p218-225.

Structural engineering

Restoring an Impaired Concrete Silo, German Gurfinkel, CF May 89 p87-99.

Structural stability

Performance of Some Structures Constructed on Chromium Ore Fills, Dorairaja Raghu and Hsin-Neng Hsieh, CF May 89 p113-120.

Subsystems

Performance and Building: Problems of Evaluation, R. A. Mohsini, CF Nov. 89 p235-242.

Suspended structures

Collapse and Repair of Tall Concrete Silos with Suspended Steel Hopper, German Gurfinkel, CF Nov. 89 p243-264.

Tanks

Ashland Tank Collapse Investigation, John L. Gross, John H. Smith and Richard N. Wright, CF Aug. 89 p144-162.

Brittle Fracture and Collapse of Large Grain-Storage Tank, German Gurfinkel, CF Aug. 89 p163-183.

Testing

Practical Quality-Controlled Construction, Harvey A. Kagan, CF Aug. 89 p191-198.

Timber construction

Roof Collapse, Taxi Cab Company Garage, Champaign, Illinois, John A. Frauenhoffer, CF May 89 p121-124.

Timbers

Roof Collapse, Taxi Cab Company Garage, Champaign, Illinois, John A. Frauenhoffer, CF May 89 p121-124.

Trusses

Roof Collapse, Taxi Cab Company Garage, Champaign, Illinois, John A. Frauenhoffer, CF May 89 p121-124.

U.S.S.R.

Assessment: U.S. Office Building in Moscow, Richard N. Wright, Nicholas J. Carino, James G. Gross and Mary Sansalone, CF Feb. 89 p2-15.

Brick Masonry: U.S. Office Building in Moscow, James G. Gross, Robert G. Mathey, Charles Scribner and William C. Stone, CF Feb. 89 p35-56.

Progressive Collapse: U.S. Office Building in Moscow, Felix Y. Yokel, Richard N. Wright and William C. Stone, CF Feb. 89 p57-75.

Structure: U.S. Office Building in Moscow, Nicholas Carino, William C. Stone, Mary Sansalone, Felix Y. Yokel, Erik M. Hendrickson, Emil Simiu, James G. Gross and Richard N. Wright, CF Feb. 89 p16-34.

Volumetric strain

Performance of Some Structures Constructed on Chromium Ore Fills, Dorairaja Raghu and Hsin-Neng Hsieh, CF May 89 p113-120.

Walls

Brick Masonry: U.S. Office Building in Moscow, James G. Gross, Robert G. Mathey, Charles Scribner and William C. Stone, CF Feb. 89 p35-56.

Water pipelines

Failures of 108-Inch Steel Pipe Water Main, Piotr D. Moncarz, John C. Shyne and George K. Derbalian, CF Aug. 87 p168-187.

Welded tanks

Ashland Tank Collapse Investigation, John L. Gross, John H. Smith and Richard N. Wright, CF Aug. 89 p144-162.

Brittle Fracture and Collapse of Large Grain-Storage Tank, German Gurfinkel, CF Aug. 89 p163-183.

Wood construction

Roof Collapse, Taxi Cab Company Garage, Champaign, Illinois, John A. Frauenhoffer, CF May 89 p121-124.

AUTHOR INDEX

Bell, Glenn R.
Project Peer Review: Results of the Structural Failures II Conference, with Frank W. Kan and David R. Wright, CF Nov. 89, p218-225

Brander, Merle
disc. (of Investigation of the Collapse of L'Ambiance Plaza, by Charles F. Scribner and Charles G. Culver, CF May 88, p58-79) with Richard Clark and John Frauenhoffer, CF Aug. 89, p203

Carino, Nicholas
Structure: U.S. Office Building in Moscow, with William C. Stone, Mary Sansalone, Felix Y. Yokel, Erik M. Hendrickson, Emil Simiu, James G. Gross and Richard N. Wright, CF Feb. 89, p16-34

Carino, Nicholas J.
see Wright, Richard N., CF Feb. 89, p2-15

Chameau, J. L.
see Santamarina, J. C., CF May 89, p78-86

Culver, Charles G.
see Scribner, Charles F., CF May 88, p58-79

del Risco, Efrain
see Levi, Enzo, CF May 89, p125-136

Derbalian, George K.
see Moncarz, Piotr D., CF Aug. 87, p168-187

Dusenberry, Donald O.
disc. (of Investigative Studies of Ceiling Collapses, by Fabian C. Hadipriono, CF Feb. 88, p44-51), CF May 89, p140-141

Estenssoro, Luis F.
Two Roof Failures Due to Water Ponding and Related Code Requirements, CF Aug. 89, p184-190

Feinen, Michael D.
Mediation that Worked: Role of OSHA in L'Ambiance Plaza Settlement, CF Nov. 89, p212-217

Frauenhoffer, John A.
Roof Collapse, Taxi Cab Company Garage, Champaign, Illinois, CF May 89, p121-124

Gross, James G.
Brick Masonry: U.S. Office Building in Moscow, with Robert G. Mathey, Charles Scribner and William C. Stone, CF Feb. 89, p35-56
see Carino, Nicholas, CF Feb. 89, p16-34
see Wright, Richard N., CF Feb. 89, p2-15

Gross, John L.
Ashland Tank Collapse Investigation, with John H. Smith and Richard N. Wright, CF Aug. 89, p144-162

Gurfinkel, German
Brittle Fracture and Collapse of Large Grain-Storage Tank, CF Aug. 89, p163-183
Collapse and Repair of Tall Concrete Silos with Suspended Steel Hopper, CF Nov. 89, p243-264
Restoring an Impaired Concrete Silo, CF May 89, p87-99
disc. (of Investigation of the Collapse of L'Ambiance Plaza, by Charles F. Scribner and Charles G. Culver, CF May 88, p58-79), CF Aug. 89, p201-203

Hadipriono, Fabian C.
Investigative Studies of Ceiling Collapses, CF Feb. 88, p44-51
disc: Donald O. Dusenberry, CF May 89, p140-141
clo: CF May 89, p141-142

Hendrickson, Erik M.
see Carino, Nicholas, CF Feb. 89, p16-34

Hsieh, Hsin-Neng
see Raghu, Dorairaja, CF May 89, p113-120

Kagan, Harvey A.
Practical Quality-Controlled Construction, CF Aug. 89, p191-198

Kan, Frank W.
see Bell, Glenn R., CF Nov. 89, p218-225

Levi, Enzo
Search for the Cause of High-Speed-Channel Revetment Failures, with Efrain del Risco, CF May 89, p125-136

Mathey, Robert G.
see Gross, James G., CF Feb. 89, p35-56

Mohsini, R. A.
Performance and Building: Problems of Evaluation, CF Nov. 89, p235-242

Moncarz, Piotr D.
Failures of 108-Inch Steel Pipe Water Main, CF Aug. 87, p168-187
disc: Richard N. Wright, CF May 89, p139
clo: CF May 89, p140

O'Rourke, Michael J.
disc. (of Roof Collapse Under Snowdrift Loading and Snow Drift Design Criteria, by Rubin M. Zallen, CF May 88, p80-98), CF Nov. 89, p266-268

Raghu, Dorairaja
Performance of Some Structures Constructed on Chromium Ore Fills, with Hsin-Neng Hsieh, CF May 89, p113-120

Sansalone, Mary
see Carino, Nicholas, CF Feb. 89, p16-34
see Wright, Richard N., CF Feb. 89, p2-15

Santamarina, J. C.
Limitations in Decision Making and System Performance, with J. L. Chameau, CF May 89, p78-86

Scribner, Charles
see Gross, James G., CF Feb. 89, p35-56

Scribner, Charles F.
Investigation of the Collapse of L'Ambiance Plaza, CF May 88, p58-79
disc: German Gurfinkel, CF Aug. 89, p201-203
disc: Merle Brander, Richard Clark and John Frauenhoffer, CF Aug. 89, p203
clo: CF Aug. 89, p203-209

Shyne, John C.
see Moncarz, Piotr D., CF Aug. 87, p168-187

Simiu, Emil
see Carino, Nicholas, CF Feb. 89, p16-34

Smith, John H.
see Gross, John L., CF Aug. 89, p144-162

Stone, William C.
see Carino, Nicholas, CF Feb. 89, p16-34
see Gross, James G., CF Feb. 89, p35-56
see Yokel, Felix Y., CF Feb. 89, p57-75

Stukhart, George
Construction Materials Quality Management, CF May 89, p100-112

Wright, David R.
see Bell, Glenn R., CF Nov. 89, p218-225

Wright, Richard N.
Assessment: U.S. Office Building in Moscow, with Nicholas J. Carino, James G. Gross and Mary Sansalone, CF Feb. 89, p2-15
disc. (of Failures of 108-Inch Steel Pipe Water Main, by Piotr D. Moncarz, John C. Shyne and George K. Derbalian, CF Aug. 87, p168-187), CF May 89, p139
see Carino, Nicholas, CF Feb. 89, p16-34
see Gross, John L., CF Aug. 89, p144-162
see Yokel, Felix Y., CF Feb. 89, p57-75

Yokel, Felix Y.
Progressive Collapse: U.S. Office Building in Moscow, with Richard N. Wright and William C. Stone, CF Feb. 89, p57-75
see Carino, Nicholas, CF Feb. 89, p16-34

Zallen, Rubin M.
Roof Collapse Under Snowdrift Loading and Snow Drift Design Criteria, CF May 88, p80-98
disc: Michael J. O'Rourke, CF Nov. 89, p266-268
clo: CF Nov. 89, p268